


PME 11 with Remote Supervisory

S = Switch, F = Fuse



PME Model #	A	B	C	D	E	F	G	H
11 w/ RS	26' 4"	18' 3"	10'	6' 4"	10'	6'	6' 3"	6'